



Vertical weakness line
Bricks only stuck to oven
arch face, no tie in or locking
of bricks as below!

Oven entrance arch
cut with a 45° bevel

